

The original kitchen faucet soon became loose and was flopping around – replaced it.

